

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

1559  
NNE  
> 1  
1.973 mi.  
10419 ft.

**MANHOLE 39372**  
**KINGS HWY AND EAST 8TH ST**  
**BROOKLYN, NY**

**NY Spills** **S110488960**  
**N/A**

**Relative:**  
**Higher**

**Actual:**  
**24 ft.**

**SPILLS:**

Name: MANHOLE 39372  
Address: KINGS HWY AND EAST 8TH ST  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 1004111 / 2010-08-25  
Facility ID: 1004111  
Facility Type: ER  
DER Facility ID: 392327  
Site ID: 437369  
DEC Region: 2  
Spill Cause: Equipment Failure  
Spill Class: C4  
SWIS: 2401  
Spill Date: 2010-07-13  
Investigator: RWAUSTIN  
  
Referred To: Not reported  
Reported to Dept: 2010-07-13  
CID: Not reported  
Water Affected: Not reported  
Spill Source: Commercial/Industrial  
Spill Notifier: Responsible Party  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2010-07-13  
Spill Record Last Update: 2010-08-25  
Spiller Name: Not reported  
Spiller Company: Not reported  
Spiller Address: Not reported  
Spiller Company: Not reported  
Contact Name: ERT  
DEC Memo: "222431. slow leak contained in manhole. Repair to end of line will be repaired. 8/25/10 - Austin - Minor drip leak from feeder - fixed? - Con Ed contained and cleaned up spill - see eDocs for more info - spill closed - end "  
  
Remarks: "Coming in from line as 1 drop per/day;Contained ."

**All Materials:**

Site ID: 437369  
Operable Unit ID: 1188048  
Operable Unit: 01  
Material ID: 2182942  
Material Code: 0541A  
Material Name: dielectric fluid  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: Not reported  
Units: Not reported  
Recovered: Not reported  
Oxygenate: Not reported